

JACOBS[®] TRANSMITTAL

To: Aaron Correll, P.G.
Team 2, VCP-CA Section
TCEQ - Remediation Division
12100 Park 35 Circle, MC-221
Austin, TX 78753

From: Jacobs

Attn: Mr. Aaron Correll

Date: May 29, 2026

Re: Quarterly Status Report, First Quarter 2026
Rohm and Haas Texas, Inc
A Wholly Owned Subsidiary of
The Dow Chemical Company
VCP No. 421

We Are Sending You:

Method of shipment: FedEx# 8722 2761 8858

Attached

Under separate cover via

Shop Drawings

Documents ☒

Tracings

Prints

Specifications

Catalogs

Copy of letter

Other: USB ☒

Quantity	Description
1	Hardcopy of Charlie Burch First Quarter 2026 Progress Report
1	Electronic Copy of Charlie Burch First Quarter 2026 Progress Report, USB

If the material received is not as listed, please notify us at once.

Texas Commission on Environmental Quality

Remediation Division Correspondence Identification Form

SITE & PROGRAM AREA IDENTIFICATION

SITE LOCATION			REMEDIATION DIVISION PROGRAM AND FACILITY IDENTIFICATION	
Site Name: Charlie Burch Pits			Is This Site Being Managed Under A State Lead Contract? ☐ Yes ☒ No	
Address 1: 25529 Richards Road			Program Area:	VOLUNTARY CLEANUP PROGRAM
Address 2:			Mail Code:	MC-221
City: Spring		State: Texas	Is This A New Site To This Program Area? ☐ Yes ☒ No	
Zip Code:	77386	County:	Harris	VCP No.: 421
TCEQ Region: Region 12 - Houston			--Leave This Field Blank--	

DOCUMENT(S) IDENTIFICATION

PHASE OF REMEDIATION	DOCUMENT NAME
1. REMEDIATION	STATUS REPORT
2.	
3.	
4.	
5.	

CONTACT INFORMATION

RESPONSIBLE PARTY/APPLICANT/CUSTOMER

Name: **Donnie Belote**
 Company: **Rohm and Haas Texas, Inc.** Phone Number: **979-238-5568** Fax Number:
 Address 1: **2301 N. Brazosport Blvd.** City: **Freeport** State: **TX** Zip Code: **77541**
 Address 2: **Bldg. B122** Email Address: **DBelote@dow.com**

ENVIRONMENTAL CONSULTANT/REPORT PREPARER/AGENT

Name: **Kristi Carter**
 Company: **Jacobs** Phone Number: **979-482-2323** Fax Number:
 Address 1: **463 This Way** City: **Lake Jackson** State: **TX** Zip Code: **77566**
 Address 2: Email Address: **Kristi.Carter@jacobs.com**

TCEQ INTERNAL USE ONLY

Document No.	TCEQ Database Term	Document No.	TCEQ Database Term
1.	STATUS UPDATE	4.	
2.		5.	
3.			

Issued: August 5, 2026

TO: Donnie Belote
Remediation Leader
Rohm and Haas Texas Incorporated
A Wholly Owned Subsidiary of
The Dow Chemical Company

FROM: Kristi Carter
Jacobs

RE: Quarterly Status Report, Second Quarter 2026
Charlie Burch Site, Spring, Texas
VCP No. 421
CN600131395/RN102970738

Activities Completed during Second Quarter 2026:

Groundwater Pump-and-Treat System in Source Area:

- The Pump-and-Treat System in the Source Area remained offline.
- Monthly Operations and Maintenance (O&M) system inspections were conducted in April, May, and June.

Groundwater Pump-and-Treat System on the 13-Acre Tract:

- The Pump-and-Treat System in the 13-Acre Tract remained offline.
- Monthly O&M system inspections were conducted in April, May, and June.

Comprehensive Groundwater Monitoring:

- Groundwater gauging and sampling of select monitoring wells was completed as part of the Sentinel event in April.
- The 2025 Annual Groundwater Monitoring Report was submitted to TCEQ in May 2026.

Activities Planned during Third Quarter 2026:

Groundwater Pump-and-Treat System in Source Area:

- The system will remain offline.
- Monthly Operations and Maintenance (O&M) system inspections.

Groundwater Pump-and-Treat System on the 13-Acre Tract:

- The system will remain offline.
- Monthly Operations and Maintenance (O&M) system inspections.

Comprehensive Groundwater Monitoring:

- Submittal of the 1st Half 2026 Underground Injection Control (UIC) update. No injections are planned during this period.
- A sitewide groundwater gauging and sampling event is scheduled to begin in August 2026.

Public Communications and Information Website:

- The following project website will be updated to include the Second Quarter 2026 Progress Report: <http://charlieburchproject.com/>.